



Overview: Part of spill impact on 12inch Imo River 2 – Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation of 7<sup>th</sup> May 2021.



Close-up: Third Party tampering with clamp. Also 1.5m distance from the clamp is a newly installed 2inch non leaking ball valve at 12 o'clock position on 12inch Imo River 2 – Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation of 7<sup>th</sup> May 2021.