




Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 5<sup>th</sup> May 2018.



Close-up: Drilled Hole on 14" Okordia – Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 6<sup>th</sup> May 2018.