


Overview: Part of spill impact on 8" Isimiri - Imogate Pipeline Right of Way at Umuelechi. Picture was taken during Joint Investigation of 5th September 2018.



Close-up: Illegal fittings on 8" Isimiri - Imogate Pipeline at Umuelechi.. Picture was taken during Joint Investigation of 5th September 2018.