


Overview: Part of spill impact on 24"Trans-Ramos Pipeline Right of Way at Odimodi. Picture was taken during Joint Investigation of 29th May 2018.



Close-up: No leak Point on 24"Trans-Ramos Pipeline at Odimodi. Picture was taken during Joint Investigation of 31st May 2018.