




Overview: Part of spill impact on 12" Imo River2 – Ogale Pipeline Right of Way at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 26th April 2019.



Close-up: Illegal Fitting on 12" Imo River2 – Ogale Pipeline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 26th April 2019.