



Overview: Part of spill impact on 8inch Umuechem – Nkpoku Deliveryline at Rukpokwu. Picture was taken during Joint Investigation of 24th August 2019.



Close-up: Illegal fitting on 8"Umuechem – Nkpoku Deliveryline at Rukpokwu. Picture was taken during Joint Investigation of 24th August 2019.