


Overview: Part of spill impact on 18'' Assa – Rumuekpe Pipeline Right of Way at Egbeda. Picture was taken during Joint Investigation of 27th February 2019..



Close-up: Illegal Fitting on 18'' Assa – Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation of 27th February 2019.