




Overview: Part of spill impact on 28'' Nkpoku – Ogale Pipeline Right of Way at Rumuowha-Eneka. Picture was taken during Joint Investigation of 8th June 2019.



Close-up: Leaking Illegal Fitting on 28'' Nkpoku – Ogale Pipeline at Rumuowha-Eneka. Picture was taken during Joint Investigation of 8th June 2019