



**Overview:** Part of spill impact on 28" Bomu Bonny Pipeline at Bodo. Picture was taken during Joint Investigation of 6<sup>th</sup> April 2020.



**Close-up:** 6" crude oil theft valve installed at 12 o'clock position on 28" Bomu Bonny Pipeline at Bodo. Picture was taken during Joint Investigation of 6<sup>th</sup> April 2020.