



Overview: Part of spill impact on 18" Assa Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 16th April 2020.



Close-up: 3nos of crude oil theft points at 12 o'clock position on 18" Assa- Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 16th April 2020.