



Overview: Part of spill impact on 36'' Nkpoku Ogale Pipeline at Agbonchia.  
Picture was taken during Joint Investigation on 21st Dec 2020.



Close-up 1: Rectangular hole of 12mmx15mm created 10 o'clock position on 36inch Nkpoku Ogale Pipeline at Agbonchia. Picture was taken during Joint Investigation on 21st Dec 2020.