



**Overview:** Part of spill impact on 20'' Trans Escravos Pipeline at Ugboegugun. Picture was taken during Joint Investigation of 5<sup>th</sup> January 2020.



**Close-up:** Illegal fitting on 20'' Trans Escravos Pipeline at Ugboegugun. Picture was taken during Joint Investigation of 5<sup>th</sup> January 2020.