



Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Rumuewhara. Picture was taken during Joint Investigation of 26th March 2020.



Close-up: 2nos 2" ball valves and 1 no 1" nipple installed at 12 o'clock position on 28" Nkpoku Bomu Pipeline at Rumuewhara. Picture was taken during Joint Investigation of 26th March 2020.