



Overview: Part of spill impact on 4" Kanbo well 5 Lima flowline at Tunu. Picture was taken during Joint Investigation 4th June 2020.



Close-up 1: 2.1km missing flowline on 4" Kanbo well 5 Lima flowline at Tunu. Picture was taken during Joint Investigation 4th June 2020.



Close-up 2: 2.1km missing flowline on 4" Kanbo well 5 Lima flowline at Tunu. Picture was taken during Joint Investigation 4th June 2020.