



Overview: Part of spill impact on 10" Diebu Creek Nun River Deliveryline at Eniwari/Onyeoma. Picture was taken during Joint Investigation of 18th July 2021.



Close-up: Rupture by suspected external impact on 10" Diebu Creek Nun River Deliveryline at Eniwari/Onyeoma. Picture was taken during Joint Investigation of 18th July 2021.